


See Part Descriptions on Back

NOTE: To order, xxx represents the 3-digit application # (vehicle type) following the 1- or 2-digit prefix, as referenced on the vehicle application list or sales receipt. Or call our Customer Service Department at 1-800-877-2588 for assistance.



* Specify: Year, Make, Model, Long-bed or Short-bed, Driver or Passenger side.

CARGOMAX™ Parts List

NOTE: To order, xxx represents the 3-digit application # (vehicle type) following the 1- or 2-digit prefix, as referenced on the vehicle application list or sales receipt. Or call our Customer Service Department at 1-800-877-2588 for assistance.

- | | | | |
|-------------------|---|------------------|---|
| 17xxx* | Black FullTilt Replacement Tarp
20161 Tarp Snap Tool Kit (w/4 Tarp Snaps)
71284 Rail Snaps (4) | 16xxx-72* | Shock Stand-off Assembly (1)
20826 Shock Stand-off Bracket (1)
22020 5/16 Nylon Nut
22041 10mm Ball Stud (1)
22043 Weld Nut (1) |
| 16xxx-10S* | Cab Bow w/Bow Ends (1) | 16xxx-73* | Latch Stand-off Assembly (1)
16xxx-71* Latch Assembly (1)
8004 Latch w/Sleeves
22043 Weld Nut (1) |
| 16xxx-11S* | Center Bow w/Bow Ends (S Bed) (1) | 16xxx-74* | Front Clamp Assembly (1)
22001 5/16-116x13/4 SHCS (1)
22022 1/4" Washer (1) |
| 16xxx-12S* | Cab Center Bow w/Bow Ends (L Bed) (1) | 16xxx-75* | Rear Clamp Assembly (1)
22001 5/16-116x13/4 SHCS (1)
22022 1/4" Washer (1) |
| 16xxx-13S* | Tail Center Bow w/Bow Ends (L Bed) (1) | 8001 | Corner Brace Assembly (1)
20830 Corner Brace
22043 Weld Nut (1)
22035 1/4"-20x3/8" SHCS (1) |
| 16xxx-14S* | Tail Bow w/Bow Ends (1) | 8010 | Pull-Down Strap w/Fasteners |
| 16xxx-31* | Front Replacement Corner (2) | 22064 | Replacement Gas Shock (1) |
| 16xxx-32* | Rear Replacement Corner (2) | Miscellaneous | |
| 16xxx-35* | Upper Pivot (Cab) Rail Assembly
2001 Cab Rail Foam Strip (30 ft.)
20838 Cab Rail Hinge Lock (1) | 22014 | 3/16" Hex Key (1) |
| 16xxx-36* | Toolbox-mounted Pivot Rail
22060 10/24 x 3/4" PPH MS (1)
22061 10/24 Nyloc Nut (1)
22062 #10 USS Flat Washer (1)
8003 Pivot Rail Foam Pad (2) | 22018 | 1/4" Hex Key (1) |
| 16xxx-45* | Tailgate Rail Assembly
2002 Tailgate Foam Strip (6 ft.) | 22026 | 3/32" Hex Key (1) |
| 16xxx-55* | Side Rail Assembly (1)
2014 Side Rail Foam Strip (8 ft.)
21221 Bow Clip w/Screw (2) | | |
| 16xxx-61* | Toolbox-mounted L Bar (1)
22060 10/24 x 3/4" PPH MS (1)
22061 10/24 Nyloc Nut (1)
22062 #10 USS Flat Washer (1) | | |
| 16xxx-63* | Replacement Toolbox (1)
1601 Toolbox Mounting Clamps (set of 2)
16xxx-62* Replacement Toolbox Mat (1)
22065 Replacement Toolbox Gas Shock (1)
22066 Replacement Toolbox Key (1) | | |
| | ** Must have lock no.# | | |
| 16xxx-70* | "L" Rod (1)
8016 "L" Rod Bumper (1) | | |

* Specify: Year, Make, Model, Long-bed or Short-bed, Driver or Passenger side.