


See Part Descriptions on Back

NOTE: To order, xxx represents the 3-digit application # (vehicle type) following the 1- or 2-digit prefix, as referenced on the vehicle application list or sales receipt. Or call our Customer Service Department at 1-800-877-2588 for assistance.



\* Specify: Year, Make, Model, Long-bed or Short-bed, Driver or Passenger side.

# FULLTILT™ Parts List

NOTE: To order, xxx represents the 3-digit application # (vehicle type) following the 1- or 2-digit prefix, as referenced on the vehicle application list or sales receipt. Or call our Customer Service Department at 1-800-877-2588 for assistance.

- |   |  |
|---|--|
| <b>6xxx-FT*</b> Black FullTilt Replacement Tarp         | <b>8xxx-72*</b> Shock Stand-off Assembly (1) |
| <b>20161</b> Tarp Snap Tool Kit (w/4 Tarp Snaps)        | <b>20826</b> Shock Stand-off Bracket (1)     |
| <b>71284</b> Rail Snaps (4)                             | <b>22020</b> 5/16 Nylon Nut                  |
| <b>6xxx-FT-8x*</b> Color FullTilt Replacement Tarp      | <b>22041</b> 10mm Ball Stud (1)              |
| <b>6xxx-FT-81*</b> Tan                                  | <b>22043</b> Weld Nut (1)                    |
| <b>6xxx-FT-82*</b> Wine                                 | <b>8xxx-73*</b> Latch Stand-off Assembly (1) |
| <b>6xxx-FT-83*</b> Red                                  | <b>8xxx-71*</b> Latch Assembly (1)           |
| <b>6xxx-FT-84*</b> Brown                                | <b>8004</b> Latch w/Sleeves                  |
| <b>6xxx-FT-85*</b> Off White                            | <b>22043</b> Weld Nut (1)                    |
| <b>6xxx-FT-86*</b> Dark Gray                            | <b>8xxx-74*</b> Front Clamp Assembly (1)     |
| <b>6xxx-FT-87*</b> Navy                                 | <b>22001</b> 5/16-18x13/4 SHCS (1)           |
| <b>6xxx-FT-88*</b> Silver                               | <b>22022</b> 1/4" Washer (1)                 |
| <b>6xxx-FT-89*</b> Carbon Fiber                         | <b>8xxx-75*</b> Rear Clamp Assembly (1)      |
| <b>6xxx-FT-90*</b> American Flag                        | <b>22001</b> 5/16-18x13/4 SHCS (1)           |
| <b>8xxx-10S*</b> Cab Bow w/Bow Ends (1)                 | <b>22022</b> 1/4" Washer (1)                 |
| <b>8xxx-11S*</b> Center Bow w/Bow Ends (S Bed) (1)      | <b>8001</b> Corner Brace Assembly (1)        |
| <b>8xxx-12S*</b> Cab Center Bow w/Bow Ends (L Bed) (1)  | <b>20830</b> Corner Brace                    |
| <b>8xxx-13S*</b> Tail Center Bow w/Bow Ends (L Bed) (1) | <b>22043</b> Weld Nut (1)                    |
| <b>8xxx-14S*</b> Tail Bow w/Bow Ends (1)                | <b>22035</b> 1/4"-20x3/8" SHCS (1)           |
| <b>8xxx-31*</b> Front Replacement Corner (2)            | <b>8007</b> Gas Shock (1)                    |
| <b>8xxx-32*</b> Rear Replacement Corner (2)             | <b>8010</b> Pull-Down Strap w/Fasteners      |
| <b>4208</b> Replacement Corner Pads (4)                 | Miscellaneous                                |
| <b>8xxx-35*</b> Upper Pivot (Cab) Rail Assembly         | <b>22014</b> 3/16" Hex Key (1)               |
| <b>2001</b> Cab Rail Foam Strip (30 ft.)                | <b>22018</b> 1/4" Hex Key (1)                |
| <b>20838</b> Cab Rail Hinge Lock (1)                    | <b>22026</b> 3/32" Hex Key (1)               |
| <b>8xxx-36*</b> Lower Pivot Rail                        |  |
| <b>8003</b> Pivot Rail Foam Pad (2)                     |  |
| <b>8xxx-45*</b> Tailgate Rail Assembly                  |  |
| <b>2002</b> Tailgate Foam Strip (6 ft.)                 |  |
| <b>8xxx-55*</b> Side Rail Assembly (1)                  |  |
| <b>2014</b> Side Rail Foam Strip (8 ft.)                |  |
| <b>21221</b> Bow Clip w/Screw (2)                       |  |
| <b>22030</b> 1/4"-20x3/4" SHCS (1)                      |  |
| <b>22042</b> Weld Nut (1)                               |  |
| <b>8xxx-70*</b> "L" Rod (1)                             |  |
| <b>8016</b> "L" Rod Bumper (1)                          |  |

\* Specify: Year, Make, Model, Long-bed or Short-bed, Driver or Passenger side.